800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

**Transmittal Letter 16-01** 

November 20, 2015

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .......EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
7-Jan-16	AZ	Mesa	Falcon Fld	5/4921	11/02/15	RNAV (GPS) RWY 4R, Amdt 1D

**AIRAC Date: 7 January 2016** 

FDC **5/4921** FFZ IAP FALCON FLD, MESA, AZ. RNAV (GPS) RWY 4R, AMDT 1D... DELETE NOTE: CIRCLING TO RWY 22R NA AT NIGHT. DELETE NOTE: WHEN RWY 4L VGSI INOP, CIRCLING RWY 4L NA AT NIGHT.

THIS IS RNAV (GPS) RWY 4R, AMDT 1E. 1510291526-PERM